HI98127 (pHep®4) · HI98128 (pHep®5)

pH and Temperature Testers

- Waterproof
 - Designed to float if accidentally dropped in water
- Up to three-point calibration (HI98128)
- Automatic Temperature Compensation
 - All readings are compensated for variations in temperature
 - Temperature displayed in °C or °F along with pH reading
- Stability indicator
 - Meter displays a tag that will disappear when the reading has achieved stability
- HOLD button
 - Freezes reading on the display to allow recording of measurement
- BEPS (Battery Error Prevention System)
 - Meter will automatically shuts off if there is not enough power to get an accurate measurement
- Battery % level at startup
- · Low Battery Indicator
- Automatic Shut-Off
 - The meter can be set to automatically turn off after 8 minutes or 60 minutes to conserve battery life in the event that the meter is left on. The auto off feature can be disabled.

The pHep®4 and pHep®5 are waterproof pH testers that have many advanced features found in more expensive portable instrumentation. These ergonomic meters feature automatic one , two or (HI98128) three-point calibration to a known buffer, automatic temperature compensation, battery percent level indicator at start up, and a stability indicator to alert the user when a stable reading has been obtained. The large multi level LCD display shows both pH and temperature simultaneously.



These meters also feature the HI73127 replaceable electrode with a stainless steel round connector. This cartridge design has no pins which could bend or break.



